

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/18/2014  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155089		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 07/24/2014	
NAME OF PROVIDER OR SUPPLIER  HERITAGE HOUSE OF NEW CASTLE				STREET ADDRESS, CITY, STATE, ZIP CODE 1023 N 20TH ST NEW CASTLE, IN 47362			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K010000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 07/24/14</p> <p>Facility Number: 000035 Provider Number: 155089 AIM Number: 100266250</p> <p>Surveyor: Mark Bugni, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Heritage House of New Castle was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (111) construction and fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, in spaces open to the corridors, and battery operated smoke detectors in all resident sleeping rooms. The facility</p>		K010000	<p>F0000 Preparation and/or execution of This Plan of Correction in general or any corrective action set forth herein, in particular, does not constitute an admission or agreement by Heritage House of New Castle of the facts alleged or the conclusions set forth in the statement of deficiencies. The Plan of Correction and specific corrective actions are prepared and/or executed solely because of provisions of federal and/or state laws. Heritage House desires this Plan of Correction to be considered the facility's Allegation of Compliance. Compliance is effective August 23, 2014. This building respectfully requests consideration for paper compliance from the Plan of Correction.</p>			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155089		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 07/24/2014	
NAME OF PROVIDER OR SUPPLIER  HERITAGE HOUSE OF NEW CASTLE				STREET ADDRESS, CITY, STATE, ZIP CODE 1023 N 20TH ST NEW CASTLE, IN 47362			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K010067 SS=F	<p>has a capacity of 95 and had a census of 49 at the time of this visit.</p> <p>All areas where residents have customary access were sprinkled. All areas providing facility services were sprinkled except the two detached wooden storage sheds.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 07/28/14.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p> <p>NFPA 101 LIFE SAFETY CODE STANDARD Heating, ventilating, and air conditioning comply with the provisions of section 9.2 and are installed in accordance with the manufacturer's specifications. 19.5.2.1, 9.2, NFPA 90A, 19.5.2.2 Based on observation and interview, the facility failed to ensure 46 of 46 resident rooms and 4 of 4 resident room egress corridors were not being used as a portion of a return air system/plenum for heating, ventilating, or air conditioning (HVAC) ductwork serving adjoining areas. NFPA 90A, Standard for the Installation of Air Conditioning and</p>			K010067	<p>The Heritage House of New Castle respectfully requests a waiver for this finding. Smoke detectors are located in the areas identified in this finding. Activation of the fire alarm system will trigger relays that shut down the air handlers in these portions of the building. Once the air handler is closed, smoke will be prevented from transferring from</p>		08/23/2014

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155089		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 07/24/2014	
NAME OF PROVIDER OR SUPPLIER  HERITAGE HOUSE OF NEW CASTLE				STREET ADDRESS, CITY, STATE, ZIP CODE 1023 N 20TH ST NEW CASTLE, IN 47362			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>Ventilation Systems at 2-3.11.1 requires egress corridors shall not be used as a portion of a supply return or exhaust air system serving adjoining areas. This deficient practice affects all residents in the facility.</p> <p>Findings include:</p> <p>Based on observations on 07/24/14 during a tour of the facility from 9:00 a.m. to 12:45 p.m. with the administrator and maintenance director, all forty six resident rooms in the facility used the four resident room egress corridors as a return air system for the air conditioning system in the facility. Based on an interview with the maintenance director on 07/24/14 at 9:30 a.m., the resident rooms in the facility are equipped with a forced air conditioned system through duct work into each resident room with the return through the exhaust vent in each resident room's shared bathroom. Heat is through radiated coils in the resident room drywall ceiling. Furthermore, based on observation of the resident room bathrooms during a tour of the facility with the administrator and maintenance director on 07/24/14 from 9:00 a.m. to 12:45 p.m., each resident room had a shared bathroom with an adjoining resident room and each shared bathroom had a door leading into the</p>				<p>one smoke zone to another. Modifications to the existing air handling system will pose a hardship for residents displaced during the installation process. The facility would also incur financial hardship for an estimated cost of \$46,000 conservatively to upgrade the air handling system to meet this requirement. The history of the facility reflects no incidents resulting from this finding. See attachments A-C.</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/18/2014  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155089		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 07/24/2014	
NAME OF PROVIDER OR SUPPLIER  HERITAGE HOUSE OF NEW CASTLE				STREET ADDRESS, CITY, STATE, ZIP CODE 1023 N 20TH ST NEW CASTLE, IN 47362			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	bathroom from the resident room. The bathroom vents were also on an electric switch that could be turned on and off by each resident. The lack of a return air duct in each of the forty six resident rooms was verified by the maintenance director at the time of observations and acknowledged by the administrator at the exit conference on 07/24/14 at 12:45 p.m.  3.1-19(b)						